



NTSB RECORD OF CONVERSATION

Adam Gerhardt
Air Safety Investigator
General Aviation Accident Investigation Division, AS-20

Date: 4/20/2017
Person Contacted: Thomas Darrow (Airport Owner, Darrow Field)
NTSB Accident Number: GAA17CA239

Narrative:

The following is a summary of a conversation that occurred with the individual named above:

- He reported that he was unaware that the accident airplane was going to land at his airport and the accident pilot did not have permission to land at the private airport.
- He reported that the pilot stated to him, after he landed, that he believed he was at Fallon Southwest Airport, rather than Darrow Field (accident airport).
- The airport owner reported that he took possession of the property surrounding the airport and the airport as well, about 20 years ago. He reported that the runway length at that time was listed as 2,600 ft.
- He reported that he would cooperate with any effort to ensure the correct runway length was listed.