



Photo 1 – View of damaged mast beam and rotor (Photo courtesy of the FAA)