



Photo 1 – View of substantial damage to horizontal stabilizer and rudder (Courtesy of FAA)