



Photo 1 – View of damage to the rudder, the vertical stabilizer and the right wing strut (Courtesy of FAA)