



NTSB RECORD OF CONVERSATION

Adam Gerhardt
Air Safety Investigator
General Aviation Accident Investigation Division, AS-20

Date: 5/31/2017
Person Contacted: Ken Hawkins (FAA Aviation Safety Inspector, Boise FSDO)
NTSB Accident Number: GAA17CA309

Narrative:

The following is a summary of a conversation that occurred with the individual named above:

- The inspector traveled to the accident site and examined the accident airplane. He reported the following findings:
 - Both brake calipers were unremarkable.
 - The parking brake was not set, when examined post-accident.
 - Nothing remarkable was found with the brake system.
- The airplane came to rest about 145 ft. off the runway to the right.