



Photo 1 – Substantially Damaged Right Wing Lift Strut (Photo Courtesy of FAA)