



Photo 1 – View of damaged nose gear support structure (photo courtesy of the FAA)