



Photo 1 – View of damaged left wing lift struts (photo courtesy of the FAA)