



Photo 1 – Substantially Damaged Tail Boom (Photo Courtesy of FAA)