



Photo 1 – Substantially Damaged Fuselage (Photo Courtesy of FAA)



Photo 2 - Substantially Damaged Left Wing Lift Strut (Photo Courtesy of FAA)