




Photo 1 – Substantially Damaged Engine Mount and Firewall (Photo Courtesy of FAA)



Photo 2 - Overview of Airplane Adjacent to Runway (Photo Courtesy of FAA)