



NTSB RECORD OF CONVERSATION

Kathryn Benhoff
Air Safety Investigator
General Aviation Accident Investigation Division, AS-20

Date: August 22, 2017
Person Contacted: Thomas Rippee
NTSB Accident Number: GAA17CA498

The following is a summary of the conversation:

The pilot reported that, during takeoff, he lost directional control. The airplane veered to the left “abruptly”, exited the runway, and struck a VASI light. The right main landing gear collapsed and the airplane nosed over.