



NTSB RECORD OF CONVERSATION

Adam Gerhardt
Air Safety Investigator
General Aviation Accident Investigation Division, AS-20

Date: 11/2/2017
Person Contacted: Technical Representative (Kolb Aircraft)
NTSB Accident Number: GAA17CA536

Narrative:

The following is a summary of a conversation that occurred with the individual named above:

- The representative reported during a telephone conversation that the Kolb Firestar II experimental kit does not include electric trim for any flight control surface.