



NTSB RECORD OF CONVERSATION

Kathryn Benhoff
Air Safety Investigator
General Aviation Accident Investigation Division, AS-20

Date: January 11, 2018
Person Contacted: Ronald Siemens
NTSB Accident Number: GAA17CA578

The following is a summary of the conversation:

The pilot reported that, during the landing roll, the airplane encountered wind, exited the runway to the left, and the wing struck a runway light.

The pilot reported that there were no preimpact mechanical failures or malfunctions with the airplane that would have precluded normal operation.