



Photo 1 – Image of taxiway and measurements (Courtesy of FAA)



Photo 2 – Image of right wing tip damage to airplane (Courtesy of FAA)



Photo 3 – Image of damage to the left fuselage, lower left windscreen and frame (Courtesy of FAA)