




Photo 1 – View of damage to the Blue blade of the main rotor system (Courtesy of FAA)



Photo 2 – View of the net with separated corner weight (Courtesy of FAA)