




Photo 1 – View of missing empennage (Courtesy of FAA)