



Photo 1 – View of damaged tail boom and main rotor blade (Photo courtesy of the FAA)