



Photo 1 – View of damage to left wing lift strut and vertical stabilizer (Courtesy of FAA)