



Photo 1 – View of damaged horizontal stabilizer (Photo courtesy of the flight school)