



Photo 1 – View of removed floor rib (Photo courtesy of the operator)



Photo 2 – View of removed floor stringers (Photo courtesy of the operator)