



Photo 1 – View of damage to the main rotor and tail rotor drive system (Courtesy of FAA)