



Photo 1 – View of damage to fuselage longerons (Courtesy of FAA)