



Photo 1 – View of damage to the lower fuselage longerons and bulkhead (Courtesy of FAA)