



Photo 1 – View of the failed left main landing gear weld (Courtesy of FAA)



Photo 2 – View of damage to left horizontal stabilizer (Courtesy of FAA)