



Photo 1 – View of damage to right-wing lift strut and windshield (Courtesy of FAA)