



Photo 1 – View of damaged gyroplane on side (Photo courtesy of the FAA)