



Photo 1 – View of bottom damaged horizontal stabilizer and elevator (Photo courtesy of the FAA)