



Photo 1 – View of damaged tail rotors (Photo courtesy of the Chief Pilot)