



Photo 1 – View of damaged lift strut (Photo courtesy of the FAA)