



Photo 1 – View of damaged vertical stabilizer and rudder (Photo courtesy of the operator)



Photo 2 – View of damaged rudder (Photo courtesy of the operator)