



RECORD OF CONVERSATION

Eleazar Nepomuceno
Air Safety Investigator
General Aviation Accident Division

Date: 06/22/2018
Person Contacted: Edwin Brondo
NTSB Accident Number: GAA18CA364

Narrative:

Edwin Brondo, the pilot of the airplane, reported during a telephone conversation, that during landing, there was a possible wind gust that caused him to veer off the runway. He and the passenger were not injured. He added that there was no preaccident mechanical failures or malfunctions that would have precluded normal operations.