



Photo 1 – View of damage to left side tunnel for the nose landing gear (courtesy of the FAA)