



Photo 1 – View of damage to the fuselage and main rotor blades (courtesy of the FAA)