



Photo 1 – View of damaged pilot side floorboards (Photo courtesy of the FAA)