



Photo 1 – View of damage to the vertical stabilizer and rudder (Courtesy of FAA)