



Photo 1 – View of accident gyroplane on left side with damaged empennage (Photo courtesy of the student pilot)



Photo 2 – Still 1 of 3 from video provided by instructor



Photo 3 – Still 2 of 3 from video provided by instructor



Photo 4 – Still 3 of 3 from video provided by instructor