



Photo 1 – View of damaged right wing lift strut and right horizontal stabilizer (courtesy of the FAA)