



Photo 1 – View of damage to the right wing lift strut, vertical stabilizer and rudder (Courtesy of FAA)