



MEMORANDUM FOR RECORD

Michael Hicks

Air Safety Investigator

(GAAID) General Aviation Accident Investigation Division December 17th 2019

NTSB Accident Number: GAA18LA062

Aircraft Registration & Make/Model: N965DS, Diamond Aircraft Industry Inc./ DA-40

Accident Location: Mesa, AZ (FFZ)

Accident Date: 13OCT2017

Subject: Memorandum for Record

In support of the National Transportation Safety Board (NTSB), Air Safety Accident Investigation involving the accident airplane, N965DS, the NTSB Investigator-in-charge, gleaned insight into the investigation from the operator's internal processes, policies and procedures analysis documents that the IIC has entered into the NTSB Docket and designated as Official Use Only. In support of the Factual report narrative, the following is a list of content derived from the operator's proprietary documents:

- A. PIC and Operator actions after the animal strike
- B. Operator Terminology
- C. Flight Instructor airplane dispatch and inspection actions subsequent to animal strike
- D. Flight Instructor actions after the Instrument Flight Rules flight return to airport