



Photo 1 – View of damage to main rotor blades (Courtesy of FAA)



Photo 2 – View of damage to tail rotor drive system (Courtesy of FAA)