



RECORD OF CONVERSATION

Eleazar Nepomuceno
Air Safety Investigator
General Aviation Accident Division

Date: 10/20/2018
Person Contacted: David Fernandez (FAA inspector assigned)
NTSB Accident Number: GAA19CA025

Narrative:

The following is a synopsis of the information provided by the FAA inspector assigned on this date:

- Private pilot landing at Lakeland Airport, using runway 09
- During landing, the airplane landed hard and bounced
- The pilot did not initiate a go around and upon touching down again, the propeller struck the runway and the nose landing gear collapsed
- Engine frame was found damaged.
- The FAA inspector added that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.
- Total flight time: 53 hours; total flight time in make and model: 53 hours