



Photo 1 – View of damage to right wing lift strut (Courtesy of FAA)