




Photo 1 – View of damaged floorboards (Photo courtesy of the flight school)