



Photo 1 – View of damaged left aileron (photo courtesy of the FAA)



Photo 2 - View of bent left aileron control rod (photo courtesy of the FAA)