



Photo 1 – View of damage to the left horizontal stabilizer, elevator and rudder (Courtesy of FAA)