



Photo 1 – View of airplane inverted with damaged empennage (Photo courtesy of unknown)