



Photo 1 – View of damaged tailboom (Photo courtesy of the FAA)




Photo 2 – View of failed hinge on owner-made dolly (Photo courtesy of the FAA)