




Photo 1 – View of damaged right-wing aft spar (courtesy of the FAA)