



Photo 1 – View of damage to the left horizontal stabilizer (Courtesy of FAA)



Photo 2 – View of damage to the bottom of the left horizontal stabilizer (Courtesy of FAA)